


## Summary Report:



2 - East Elevation



Datum: NAD83 17N Northing: 4779940 Easting: 422079

Structure Name: BMROSS File #:  MTO #: Main Hwy / Road #: Bridge Condition Index (BCI):  10 CRV: \$549,000Road Name: Kinnaird Road 

Inspection Date: 2025-10-28

Structure Location: 0.5 km South of Ipperwash Road/Ravenswood Line 

Next Inspection: 2027-01-01

Condition Summary: Replacement recommended  Recommended Timing: Within 1 Year Current Load Limit: N/A Overall Comments: Structure is in poor condition. Replacement is recommended within 1 year. 

## Repair / Rehabilitation:

Element:	Work Required	Period	Cost
Culverts	Replace structure	Within 1 yr.	\$400,000
Various	Associated Work		\$189,000
		Total	\$589,000

## Additional Investigations:

## Maintenance Needs:

**Inventory Data:**

Structure Name:				Crossing Type:
Main Hwy / Road #:				On <input checked="" type="checkbox"/> Under <input type="checkbox"/>
Road Name:	Kinnaird Road			Northing: 4779940
Structure Location:	0.5 km South of Ipperwash Road/Ravenswood Line			Easting: 422079
Owner(s):	Municipality of Lambton Shores			Heritage Designation: Not Designated
MTO Region:	Southwestern			Road Class: Local
MTO District:	Chatham			Posted Speed: 80 No. of Lanes: 2
Current County:	Lambton			AADT: 50-199 % Trucks:
Geographic Twp.:	BOSANQUET			Special Routes:
Structure Group:	Culverts			Surface Type: Gravel
Structure Type:	CSP Arch Culvert			Detour Length Around Bridge: (km)
Total Deck Length:	3.05	(m)		Fill on Structure: 0.4 (m)
Overall Str. Width:	18	(m)		Skew Angle: 5 (Degrees)
Total Struct. Area:	54.9	(sq.m)		Direction of Structure: North/South
Roadway Width:	6.4	(m)		Min. Vert. Clearance:
Number of Spans:	1			Bridge Condition Index: 10
Span Length(s):	3.4	(m)		
MTO Number:				BMROSS File Number:

**Historical Data:**

Year Built:	1970 est.	Last Biennial Inspection:	2023
Current Load Limit:	(tonnes)	Last Evaluation:	
Load Limit By-Law #:		Last Enhanced Inspection:	
By-Law Expiry Date:		Enhanced Access Equipment:	

**Field Inspection Information:**

<b>Date of Inspection:</b> 2025-10-28	<b>Inspection Type:</b> OSIM Inspection	<b>Next Detailed Inspection:</b> 2027
<b>Inspector:</b> Nic Gowing		
<b>Inspecting Firm:</b> BMRoss & Associates Limited		
<b>Others in Party:</b>		
<b>Equipment Used:</b> Hammer, Camera, Measuring Tape, Chain		
<b>Weather:</b> Sunny		
<b>Temperature:</b> 8 °C		

**Additional Investigations**

Investigation Description	Note	Priority	Estimated Cost
Concrete Substructure Condition Survey		N/R	\$0
Detailed Coating Condition Survey		N/R	\$0
Detailed Timber Investigation		N/R	\$0
Post-Tensioned Strand Investigation		N/R	\$0
Underwater Investigation		N/R	\$0
Fatigue Investigation		N/R	\$0
Seismic Investigation		N/R	\$0
Structure Evaluation		N/R	\$0
Monitoring Deformations, Settlements, or Movements of Crack Widths		N/R	\$0
Detailed Deck Condition or Corrosion Potential Survey		N/R	\$0
Non-destructive Delamination Survey of Asphalt-Covered Deck		N/R	\$0
<b>Total Cost:</b>			<b>\$0</b>

**Overall Structure Notes:****Bridge Condition Summary:** Replacement recommended**Recommended Timing:** Within 1 Year**Overall Comments:** Structure is in poor condition. Replacement is recommended within 1 year.**Replacement Value:**

Structure Type:	CSP Culvert	Structure Area:	61 (sq.m)
Replacement Cost:	\$ 549,000	Complexity Factor:	2
		Price per sq. m.:	\$ 4,500.00

*Note: Replacement cost calculation is based on the above price per square metre, the total deck or structure area for the existing structure and the chosen complexity factor. This cost may not be a suitable value when budgeting to replace a structure.*

**Suspected Performance Deficiencies**

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections and rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

**Maintenance Needs**

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
05 Bridge Deck Joint Repair	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

**Repair / Rehabilitation:**

Element:	Work Required	Period	Cost
Culverts	Replace structure	Within 1 yr.	\$400,000
<b>Repair/Rehabilitation Sub-Total:</b>			<b>\$400,000</b>

**Associated Work Required:**

Mobilize / Demobilize		\$25,000
Approaches	Allowance for Road Widening	\$10,000
Traffic Control / Detours		\$15,000
Utilities		\$0
Right of Way	Legal Survey	\$4,000
Environmental Study	Approvals, Hydrology, Geotech	\$25,000
Engineering		\$55,000
Other		\$0
Contingencies		\$55,000
		<b>Associated Work Sub-Total:</b>
		<b>\$189,000</b>
		<b>Total Cost:</b>
		<b>\$589,000</b>

**Justification:**

Replacement costs assume a similar span concrete box structure.

Element Data:					
Element Group:	Culverts			Length:	3.05
Element Name:	Barrels			Width:	18.0
Location:				Height:	2.35
Material:	Corrugated Steel			Count:	
Element Type:				Total Quantity:	152.7 m <sup>2</sup>
Environment:	Benign			Limited / Not Inspected:	<input type="checkbox"/>
Protection System:	None			BCI - Element Condition Values:	
Condition Data:	Excellent	Good	Fair	Poor	TEV
			25% (38.17)	75% (114.52)	\$53,445
Comments:	Several locations along bottom with perforations. Most of the bottom has very severe section loss. Minimal embedment into channel. Some erosion at corners.				
Performance Deficiencies:					
Recommended Work:	Replace structure.				Recommended Timing: < 1 year
Maintenance needs:					
Maintenance work:					Maintenance Priority:



1 - Looking South




2 - East Elevation




3 - Barrel View



4 - Perforations at East End



5 - Interior Perforations and Section Loss



6 - Perforations at West End